Bently Nevada Rub, Morton Effect, Parametric Excitation, and Shaft Crack in Rotating Machinery - Real Cases

John J. Yu, PhD **Senior Technical Manager** Machinery Diagnostic Services

T +1 678 844 5753 | M +1 775 720 3239 4200 Wildwood Parkway | Atlanta, GA 30339 USA

April 2, 2019



Copyright 2018 Baker Hughes, a GE company, LLC ("BHGE"). Bently Nevada and Orbit logo are registered trademarks of BHGE in the United States and other countries. All product and company names are trademarks of their respective holders.



Presenter Bios



Dr. John Yu joined Bently Rotor Dynamics Research Corporation in 1998, followed by General Electric - Bently Nevada in 2002. He has performed not only rotor dynamic research but also machinery vibration diagnostics for customers worldwide, and is now Senior Technical Manager of Machinery Diagnostic Services at Bently Nevada. He has over 50 technical papers in refereed journals and conference proceedings. He holds a PhD in Mechanical Engineering from University of Alberta, and is an ASME Fellow.





Abstract

This presentation discusses rub, Morton effect, parametric excitation, and shaft crack cases in rotating machines. Rub occurs more often besides unbalance and misalignment. The current rub topic covers all types of rub. The Morton effect has similar vibration pattern as the Newkirk effect, though it occurs not that often. Parametric excitation here is referred to subharmonic behavior such as $\frac{1}{2}X$ vibration, due to either rub or bearing looseness. Since $\frac{1}{2}X$ is touched here, shaft crack manifested by 2X vibration is also discussed briefly.



Rub Diagnostics



Copyright 2018 Baker Hughes, a GE company, LLC ("BHGE"). All rights reserved.

erved

1. Introduction

Almost always the case in the **Types of rub** field on turbomachinery

- ${ \bullet }$
- resonance speed
- **Reverse precessional full annular rub (dry whirl/whip)**
- \bullet as $\frac{1}{2}X$ at speed of 2 times resonance)
- Morton effect (technically not a rub) \bullet





Newkirk effect (thermal rub behavior) manifested by 1X vibration excursion

Forward precessional full annular rub with 1X vibration when passing

Bouncing type of rub with fractional frequency (parametric excitation such



1. Introduction (Cont.)

Root-causes of 1X vibration excursion:

Newkirk effect

Thermal transient

Steam loading

Changes in alignment

Changes in unbalance

Morton effect



1. Introduction (Cont.)

Thermal Bow Effect of Rub – causing 1X amplitude & phase to change



Rubbing Spot

Seal

 $\vec{r} = A(t)e^{j[\Omega t - \alpha(t)]}$

where

- A(t): Amplitude varying with time
- $\alpha(t)$: Phase lag varying with time

A New High Spot and Rubbing Location

Increased 1X Orbit

- 9-MW Steam Turbine Generator
- 4350 rpm on turbine and 1800 rpm on generator
- High turbine vibration tripped the unit

on generator nit

Turbine inboard vibration increased from 1 mil pp to 4 mil pp 20 minutes after reaching rated speed

1X Bode plots from proximity probes

- **High vibration presented** at both high and low speed range.
- When speed is low, high vibration is mainly due to shaft bow.

1X Bode plots from seismic transducers

- **High vibration only** presented at high speed or critical speed ranges.
- Thermal shaft bow at low speed cannot be verified.

1X polar plots from proximity probes

5 mil pp FULL SCALE

CW ROTATION 5 mil pp FULL SCALE

- **1X reverse rolling** vectors at rated speed or steadystate condition.
- Less meaningful when speed is changing or in transient condition.

CW ROTATION

1X polar plots from seismic transducers

0.5 in/s pk FULL SCALE

CW ROTATION 0.5 in/s pk FULL SCALE

1X reverse rolling vectors at rated speed or steadystate condition.

Less meaningful when speed is changing or in transient condition for rub diagnostics.

CW ROTATION

Waterfall plots from proximity probes

Half Spectrum

- Super-harmonic components (2X, 3X, etc.) could exist all the time due to runout on probe-viewing area whether a rub occurs or not.
- **Rich harmonics may** not be a good indicator of rub from proximity probes

- True readings of superharmonics if any from seismic transducers.
 - **Rich harmonics is a good** indicator of rub from seismic transducers.

Signs of rub as seen from turbine rotor and top case

Seal clearance setup was found to be incorrect!

Copyright 2018 Baker Hughes, a GE company, LLC ("BHGE"). All rights reserved.

Case 2: Transient data only

- 28-MW Steam Turbine Generator
- 3000 rpm on turbine and 1800 rpm on generator
- High generator vibration tripped the unit

ator O rpm on generator ped the unit

Case 2: Transient data only (Cont.)

1X Bode plots from proximity probes

- Significantly higher vibration during shutdown than during startup.
- This indicates thermal bow due to a rub.

Case 2: Transient data only (Cont.)

Orbit plots (waveform-compensated)

Case 2: Transient data only (Cont.)

Rich superharmonic components due to distorted orbit shapes

Rub diagnostic rules in steady-state vs. transient condition

- of rub.
- indications of rub.
- In transient conditions, trend or polar plots may give less meaningful information for rub diagnostics.
- normal.

In steady-state condition, polar plots give the most meaningful indications

In transient conditions, bode and orbit plots may give the most meaningful

 Distorted orbit may pinpoint the rub location in steady-state/transient condition. But many rubs can occur when orbits are very smooth and look

Summary and Discussion

Type of plot	Speed condition	Key features
Trend	Stead-state	Mainly scree
Polar	Stead-state	How 1X vect
Bode	Transient	Comparison
Orbit	AII	Any distorte
Waterfall	AII	Onset of rich

- Selection of vibration data plots for rub diagnostics
 - to look for
 - ning to see If 1X vibration excursion occurs
 - ors are rolling against shaft rotation
 - of shutdown vs. startup data
 - d orbit (waveform-compensated)
 - harmonics

There are more rub cases including those due to grounding brush (forward 1X rolling vector) in the following paper:

Yu, J. J., 2013, <u>Rub Diagnostics Based on Vibration Data</u>, ASME Paper GT2013-94203, International Gas Turbine & Aeroengine Congress & Exhibition, San Antonio, Texas.

• Oil coking:

due to heating of oil from hot steam, gas flow, etc.

- Oil varnishing:
- due to oil quality, over loading, electro-static discharge (ESD),
- degradation of oil, etc.

✓11∨ MR ✓11∨ ✓11∨	/XT31 C310 /XT31 C310	010 – 1_Trai 010 <mark>(=</mark> 1_Trai	—45° From 24 =45° From 24	Right IJAN201 Right IJAN201	t 1X 9 13:38 t Dire 9 13:38	3:33 To : ect 3:33 To :	25JAN2(25JAN2(019 13:3 019 13:3	8:33 8:33		Historic Historic	al al
*				24JAN2019 17:38				24JAN2019 21;38				
	0	BELOV	V MIN AM	P		 	I	· ·			· · ·	
PHASE LAG: 5 deg/div	15	 -					•					
	30	-	· · ·			' 		· · ·	1		· · ·	· ·
	45	-	· · ·				•	· ·			· ·	•
	60	-	· · ·			l I	•	· ·			· ·	•
	75	_							-			
AMPLITUDE: 1 um pp/div	15	-	· · ·			 		· · ·		 	 	
	10	- - -	· · ·	· · ·		 		· · ·			· · ·	
	5			· · ·		 				 	· · · ·	· · ·
	Π	- -	· · ·	· · ·		 		· · ·			· · ·	
	13: 24JAN	l :38 N2019	, ,	I	17. 24JAN	l :38 N2019			21: 24JAN	 :38 \2019		' <u>אוד</u>

Forward full annular rub case on a rotor-kit

Bently Nevada

Comparison of direct responses between rub and no-rub cases

Note:

 Resonance speed region with rub is greatly increased during runup.

• The rotor may bounce inside the seal with almost continuous contact.

Forward full annular rub case on a rotor-kit

Comparison of 1X responses between rub and no-rub cases

Note:

- Synchronous (1x) precession is dominant.
- 1x phase angle changes smoothly during runup, quite differently compared with no-rub cases.

31

Reverse full annular rub case on a rotor-kit

- Triggered during startup without outside disturbance
- Direct/orbit response

Note:

- Three regions are distinguished during transition from contact initiation to reverse full annular rub:
 - (1) Dominant 1x forward
- 2000 (2) Dominant 1x reverse and then transitional speed-independent reverse

(3) Reverse full annular rub with a fixed frequency

.

Reverse full annular rub case on a rotor-kit

Bently Nevada

pp/div

2 mil

AMPLITUDE:

Note:

- Synchronous 1x response component almost disappears during the full annular rub.
- Three speed regions during contact :
 - (1) Dominant 1x forward
 - (2) **Dominant 1x reverse**
 - and then speed-independent reverse
 - (3) Reverse full annular rub with a fixed frequency (2300 cpm in this case)

33

dry whirl/whip, are typically not seen in real machines.

The following papers can be viewed in ASME Journal of Engineering for Gas Turbines and Power for detailed information

Yu, J. J., Goldman, P., Bently, D.E., and Muszynska A., 2002, <u>Rotor/Seal Experimental and Analytical</u> Study on Full Annular Rub, Transactions of the American Society of Mechanical Engineers, Journal of Engineering for Gas Turbines and Power, Vol.124, pp.340-350.

Yu, J. J., 2012, On Occurrence of Reverse Full Annular Rub, Transactions of the American Society of Mechanical Engineers, Journal of Engineering for Gas Turbines and Power, Vol. 134, 012505.

Full Annular Rub, including both forward and reverse

Morton Effect

Morton Effect

- "Rubbing" on oil film.
- Looks like seal rub, but no rub sign on stationary parts.
- Often very smooth 1X rolling vector on polar plot. Looks like smooth orbit on polar plot.
- Typically on overhung compressor bearing







Bently Nevada



Bently Nevada



Bently Nevada



Parametric Excitation



Copyright 2018 Baker Hughes, a GE company, LLC ("BHGE"). All rights reserved.

erved

Subsynchronous vibration

- These two types of vibration can be confused. \bullet
- Oil whirl, sometimes called half-frequency whirl, is not \bullet at fractional ¹/₂X frequency. It is typically below 0.5X.
- Though high resolution spectrum helps to determine \bullet the frequency (unable to zoom to "0" Hz), orbits with **Keyphasor[®] dots, provide the best tool to distinguish** between these two types of vibration.



Non-fractional (such as oil whirl, approx. 0.35X to 0.47 X)

Fractional or subharmonic (such as ½X, ½X, ¼X, etc.)



Introduction

0.47X (Oil Whirl)





Introduction

¹/₂X Vibration



ROTATION: X TO Y (CCW)

Keyphasor dots are locked on the orbits





Y: BRG 3Y-Sync Waveform#2 AC COUPLED mil/div -X: BRG 3X-Sync Waveform#2 ÷ 150 200 250 100 50 0 10 ms/div

Copyright 2018 Baker Hughes, a GE company, LLC ("BHGE"). All rights reserved.

anuad

Theory

Equation of motion of the Jeffcort model: $M\frac{d^{2}x}{dt^{2}} + D\frac{dx}{dt} + K(\Omega t)x = mr\Omega^{2}\cos(\Omega t - \varphi)$

If we have nonlinear step-changing stiffness $K(\Omega t)$ within each synchronous 1X vibration cycle









Thus, the principal instability region is approx. determined by

This is exactly the $\frac{1}{2}X$ vibration.



Theory

- $|\delta 1| < |\varepsilon|$
- and the unstable solution is dominantly composed of $\cos \tau$ and $\sin \tau$ terms.

Theory

$$2\omega_n < \Omega < 2\omega_n \sqrt{1 + \frac{\alpha \Delta K}{\pi K_0}},$$
 and

$$2\omega_n \sqrt{1 + \frac{\alpha \Delta K}{\pi K_0}} < \Omega < 2\omega_n,$$

where $\omega_n = \sqrt{\frac{K_0}{M}}$



- Assume q_{α} (range where ΔK occurs) is small. $\longrightarrow \frac{\alpha}{2} \approx \frac{\alpha}{2}$
- Thus the unstable speed region due to step-changing stiffness:
 - for $\Delta K > 0$ Normal-tight

for $\Delta K < 0$ Normal-loose



- **3600-rpm, 25 MW steam turbine generator.**
- Journal bearings.
- \bullet onset of ¹/₂X vibration.



Case One

Vibration excursion from approx. 2 mil pp (~50 µm pp) to 12 mil pp (~300 µm pp) at Bearing #3 at 2 MW, due to

Case One



Copyright 2018 Baker Hughes, a GE company, LLC ("BHGE"). All rights reserved.

anuad

Shaft centerline plot at Bearing #3



Case One

E company, LLC ("BHGE"). All rights reserved.

Orbit plots at Bearing #3

 \mathbf{T}



0.5 mil/div

0.5 mil/div



Case One

÷÷



Waterfall plot from Bearing #3 Y-Probe



Indicative of natural frequency at near 1800 cpm or half of the running speed (most likely due to suppressed oil whip), prior to onset of $\frac{1}{2}X$.



Case One

Spectrum plot from Bearing #3 Y-Probe



Primarily ¹/₂X component without significant harmonics



Case One

Inspection on Bearing #3





Case One

- **Oversized bearing. Diametral clearance** 0.005 inch (127 µm) higher than its spec
- Damage on the bearing surface.







Case One



There are more $\frac{1}{2}$ X vibration cases in the following paper:

Yu, J. J., 2010, Onset of 1/2X Vibration and Its Prevention, Transactions of the American Society of Mechanical Engineers, Journal of Engineering for Gas Turbines and Power, Vol. 132, 022502.





- 3600 rpm, LP speed 1800 rpm, and rated output 750 MW.
- seismic sensors. Data collection performed to support its startup after outage.





Case Two

Cross-compound steam turbine generator unit with HP speed

• Vibration monitored by proximity probes at each bearing, plus

Problem:





Case Two

Trend plots



Bently Nevada

Case Two

Waveform-compensated orbits:





Case Two

Changing with time at 1800 rpm



Bently Nevada

Case Two

Polar plot





Case Two

Waterfall plot

Abnormal ¹/₂ X and its multiples during shutdown



Case Two

Case Two





991 rpm as resonance or critical speed during coast-down

Direct, 1X, and ½X bode plots plots 1/2X maintained until 1631 rpm during coast-down





Case Two

Shaft centerline plots

Abnormal shaft centerline plot at Brg#5



Analysis

Root-cause of much higher vibration:

- 1X and ½X components ? Yes
- Shaft bow ? Yes
- Change in bearing condition ? Likely at Brg#5 > Normal shaft centerline plots except at Brg#5



> 1X, followed by dominant $\frac{1}{2}X$ (20 mil pp), thus tripping the unit. ¹/₂X maintained above 1631 rpm during shutdown

High runout at low speed during shutdown (10 mil pp)

Analysis

Root-cause of much higher vibration (Cont.):

• Rub? - Yes

>1X vectors changed at constant speed Distorted orbits at Brg#5 Likely due to changes in shaft centerline position What caused ¹/₂X vibration ? – oversized bearing

900 cpm < 991 cpm. Normal-tight or normal loose?



- > Much higher runout during shutdown, indicative of shaft bow
- $\gg \frac{1}{2}$ X occurred at 1631 to 1800 rpm during shutdown. The first critical speed is 991 rpm. Thus, the $\frac{1}{2}$ X frequency was at 815-

Analysis

Root-cause of much higher vibration (Cont.):

• Bearing damage? – Most likely > At constant speed of 1800 rpm and during coast-down, shaft centerline position was far beyond the bearing clearance boundary at the bottom at Brg#5. > Unfortunately, bearing metal temperature reading was invalid due to the sensor issue.



Conclusions

- Brg#5 appeared to have been damaged based on shaft centerline position.
- Rub seemed to occur, causing varying 1X vibration and
- ½X vibration occurred due to oversized bearing (normalloose).



distorted orbits, plus significant shaft bow during shutdown.

Recommendations:

- Open Brg#5 for inspection
- Check rub locations



Case Two

Inspection & Findings :

 The findings indeed indicated Brg #5 bearing wiped, mostly at the left bottom with additional 42 mils clearance due to wear beyond as-left clearance of 24 mils in vertical direction, matching the diagnosis. Obviously the wear was due to journal rubbing against the babbitt surface.

Bently Nevada

Case Two



Babbitt wear at the left bottom

Babbitt material transferred to e to

generator





Copyright 2018 Baker



Inspection & Findings :

- It was found that a fine strainer was mistakenly left, causing oil reduction and starvation, and finally wiping the bearing.
 Bearing was shipped offsite to be re-spun.
- Rubs occurred on inner and outer oil deflectors at Brg #5 as well as that at adjacent Brg #4 generator side. All three were shipped offsite for teeth replacement.
- Brg#5 H_2 seal casing oil deflector rubbed and replaced with new one.
- Adjacent Brg #4 turbine side oil deflector clearance and alignment acceptable.



Inspection & Findings :

dimensions were verified to be acceptable.



No damage was observed on Brg#5 journal surface, and its

Resolution:

The bearing was repaired and re-installed correctly.

Damaged oil deflectors were replaced with new ones.







Case Two

Final shaft centreline plots:





Lessons Learned:

- Correct assembly after outage should be ensured to avoid costly repairs. All important sensors should be ensured working properly.
- The ½X vibration up to 20 mil pp was due to the increase in bearing clearance, not simultaneously due to a rub against the bearing wall.
- However, rubs did occur, which first damaged bearing babbitt surface and resulted in a change in shaft centerline position. This change caused the shaft to rub against oil deflectors. All these rubs were indicated by 1X vibration excursions.
- Shaft centerline is one of the most important plots in machinery diagnostics. It was used to diagnose bearing damage correctly when bearing metal temperature reading was invalid.
- Had the vibration issue be simply treated as rub, followed by re-start without in-depth data analyses and actions, further catastrophic damages would have occurred.





Shaft Crack Diagnostics -1X & 2X vibration monitoring



Copyright 2018 Baker Hughes, a GE company, LLC ("BHGE"). All rights reserved.

erved

Machine train diagram

Turbine

- O Turb EXH X Direct Gap 1X
- O Turb EXH Y Direct Gap 1X
- ✓ Turb EXH X Velocity Direct 1X
- C Turb EXH Y Velocity Direct 1X

Turbine Inlet

Turb InletX റ് Direct Gap 1X Turb Inlet Y \mathbf{b} Direct Gap 1X Turb Inlet X Velocity đ Direct $1\times$ Turb Inlet Y Velocity \sim

Direct

1X

















Bently Nevada











Direct compensated orbit of the TURB EXH bearing at 3035 RPM during shutdown







Inspection and Finding

Air separator sleeve

Holes admit air for cooling turbine disks

Air separator sleeve bolts to torque tube via this flange

Balance-weight holes

Torque tube

Last compressor stage



Cracks on torque tube that joins the compressor and turbine sections of the rotor





